





Assembly Manual






①1) Chassis Center Pivot (open Bag 1 to 4)





02 Chassis Center Pivot




V1.0 (20-July-2022)




















07 Ball Differential (open Bag 6, 7, 8)
















11) Ball Differential




Apply Ball Diff Grease and insert balls to the spur gear hub.














15 Rear Bulkhead (open Bag 9)







V1.0 (20-July-2022)



























23 Side Spring






















28 Damper Mount



















M2*2 set screw (Steel)










Center Spring
(may need some force to get
it in place, no worry just push
it, spring is flexible)























Droop screw setup




Screw Tip come out around 0.3mm














37 Steering Crank




38 Upper Arms








40 Steering Knuckle







41 Steering Knuckle




42 Front Wheel Shaft





























49 Adjustment of the Side Spring



Use 1.3 hex tool, to adjust the side spring, make it barely touch the surface of rear bottom plate. Excess pre-load of spring will make the car loose rear grip.





Gear Ratio	10	11	12	13	14
51	5.10	4.63	4.25	3.92	3.64
52	5.20	4.72	4.33	4.00	3.74
53	5.30	4.81	4.41	4.07	3.78

For 3500kv motors, recommend ratio is around 4.00