



## Step 01

Make 4 pcs




## Step 02

Screw in the ball cap to the damper tube.





Use 0.9mm hex tool to hold the damper tube



## Step 03

Insert the O-Ring to the groove of the spring tension collar.



Apply damper grease , #25000 or #35000 is recommended.

